



# Robot-assisted screwdriving system RSF

For flow drilling screws with automatic feed system


## Robot-assisted screwdriving system

For flow drilling screws with automatic feed system



### Screwdriving process phases:

- 1. Tip of fastener heats the material through high thrust and high RPM
- 2. Material plasticized by conical screw tip
- 3. Cylindrical passage formation
- 4. Chip-free channelling of a metric True to gauge screw thread
- 5. Normal screwdriving phase
- 6. Torque-controlled screw tightening



#### **Spindle Technical Data:**

Mounting dimensions: Spindle dimensions: Weight of RSF spindle: Transducer: Spindle Speed:

Maximum axial force with 5 bar: cycle time for screwing in a screw: aprox. 6 s (start / start) Pneumatic system:

Energy supply provided by customer:

 $W \times H \times L = ca. 810 \times 500 \times 2500 \text{ mm}$  $W \times H \times L = ca. 730 \times 230 \times 250 \text{ mm}$ 

approx. 35 kg up to 15 Nm up to 5000 RPM 1.500 N

Operating pressure 5 bar

Power required 3 phase, 400 v, 50 hz.



#### Weber Schraubautomaten GmbH

Hans-Urmiller-Ring 56 D-82515 Wolfratshausen Phone +49 (8171) 406-0 Fax +49 (8171) 406-111 info@weber-online.com www.weber-online.com

#### **Features:**

- Straight version for standard applications
- Compact version available for limited access applications
- Tool-less screwdriving tool replacement
- Screw seating height is relative to component surface
- Controllable thrust force
- Points system available for processing different screw lengths
- C50S controller with process & screwdriver control and optional touch screen
  - Possible customer interfaces to C50S: a) Digital b) Interbus c) Profibus
- Cable and hose package suitable for robots
- Minimum load-bearing capacity of robot 200 kg